1186072 - R8 SDMS

### STATE OF COLORADO

#### COLORADO DEPARTMENT OF HEALTH

222 So. 6th St., Room 232 Grand Junction, Colorado 81501



Roy Romer Governor

Thomas M. Vernon, M.D. Executive Director

July 29, 1988

Robert L. Dent Anaconda Minerals Co. Western Minerals Project 555 17th Street Denver, CO 80202

Re: Annual Inspection of Wastewater Treatment Facilities for Anaconda Minerals Co. - St Louis Tunnel, CPDES Permit No. CO-0029793, Dolores County

Dear Mr. Dent:

Enclosed is a copy of my inspection performed on July 6, 1988. This is a follow-up to an earlier sampling inspection performed by David Dauber on June 30, 1988. As stated in Mr. Dauber's report, the Division feels the facility is being properly operated.

After closer inspection of the treatment facilities we recommend the following:

- 1) Check the accumulation of solids in the first two settling ponds to insure there is maximum detention time and no short-circuiting is occurring.
- 2) An influent flow measuring device prior to the first pond should be installed to demonstrate that the ponds are not leaking. During my inspection it appeared the two upper ponds may be leaking into the Dolores River.
- My inspection revealed that the discharing "artesian" wells appear to be geothermal wells and their discharge is not part of the discharge from the facility as stated in your permit. I am recommending to our Permits Section that your permit be re-reviewed to determine if a permit is required for the geothermal wells.

If you have any questions, please call me in the Grand Junction Office at 248-7154.

Sincerely,

James B. Horn District Engineer

Water Quality Control Division

JBH/mb

cc: San Juan Basin Health Unit

Permits & Enforcement Section, CDH

Field Services, Denver

EPA, Region VIII Sharon Ferdinandsen

Leslie Simpson (Inspection Report only)

Jim Horn File Colorado Department of Health-FS&M Section

# CDPS/NPDES FACILITY INSPECTION REPORT

Plant Class "C"

TIONAL BATA CACTEM CODIN			
SECTION A: NATIONAL DATA SYSTEM CODIN Transaction Code CDP8/NPDE3		pection Type Inspector	Fac Type
1 25 3 COOO2979311 1	12 8 8 0 7 0 6 17	اهاه،	20 2
	Remarks (See Code)	Operator in Charg	
Reserved Facility Evaluation Rating BI 71 n	72 73 1 7 <sub>1</sub>	Class & Cert. #	
SECTION B. FACILITY DATA			
Name of Facility Inspected Anaconda Minerals—Western M	finerals Projects	Entry Time ☐ AM 2:00 ☑ PM	0-13-00
Physical Location St Locatis Tunnel & mile North o	f Rico		Permit Expiration Date 12-31-92
Name(s) of On-Site Representative(s) Neil Muldoon	Operator		Phone Nots 967-2871
Address * 555 17th St.	Denver	CO State	80202
Name of Person Conducting Inspection James B. Horn	District Engine	er	
SECTION C: AREAS EVALUATED DURING INSE	PECTION		
	rginal, U = Unsatisfactory, N = Not Eval		
Permit   Flow Measurement   Records/Reports   Laboratory	Pretreatment Compliance Sche	<b>—</b>	ations & Maintenance ge Disposal
Facility Site Review Effluent/Receiving Wa	sters Self-Monitoring P	rogram Othe	r.
SECTION D. OPERATION MAINTENANCE			
Operator in Charge:		No. of Operato	rs:
Budget: \$ Salaries: \$	_ Utilities: \$	Maintenance	: \$
Chemicals: \$ Sludge: \$	Other: \$ Unit	Trmt. Cost/1,000 gais	s: \$
Collection System: No. of Taps:	<u>.                                    </u>	No. of Lift Station	ns:
Pop. Eq. Served: I/I Program		reatment Process: _	
Design Capacity: Hydraulic:	Organic:		
Present Loading: Hydraulic:	Organic:		Cap
SECTION E: MONITORING AND COMPLIANCE		<u> </u>	
Type and location of flow measuring equipment:		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
	Accurate (Ves/No):	If (No) Com	ment:
	· · · · · · · · · · · · · · · · · · ·		
Lab performing DMR analysis:	•	-	
Analysis in compliance with approved procedures, (Yes			
Analysis in compliance with approved procedures, (res	(NO): IT (NO	), Comment:	
Sampling in compliance with permit requirements, (Yes		\ Commont	<del></del>
campung in compliance with permit requirements, (165	(140) II (140	, Comment.	· · · · · · · · · · · · · · · · · · ·
Physical description of receiving stream:			
Does facility meet permit requirements:		•	
List facilities deficiencies:		ring	Kar Barrer
Comments:			
	•		

### INDUSTRIAL INSPECTION REPORT

## I. OWNERSHIP

County Dolor	es	CDPS No. C	0-0029793	Date 7-6-88
Facility Name	Anaconda Miner	als Co St	. Louis Tunnel	
Legal Owner	Western Minera	ls Projects	Robert L. Den	t, Manager
Mailing Addres	s 555 17th Str	eet		
Cit	y Denver	· · · · · · · · · · · · · · · · · · ·	State CO	Zip 80202
Facility (Phys	ical Location)_	な mile N	North of Rico	
Business Phone	293-7938		Emergency Phone_	967-2871
II. Facility Plant Products	Lead, Zinc, Si	lver, How	vever presently ina	active
Present Produc			Design Production	on Rate0
Raw Materials_	Metal Ore			
	terials Contains			nt for precipitation
		and sedime	entation.	
	·			
acility Evalua	tion vs. Permit	Recommend	influent flow mea	suring device to
letermine if fi	rst few ponds a	re exfiltrat	ing.	
<del></del>	<del></del>	<del></del>		

Pa	ge	2

Facili	ty Deficiencies	First	two pond	s need cle	aning.	"art	esian wel	ls" are	_actua]
geothe	rmal wells and	are con	tributing	dissolved	solids	to th	e Dolores	river.	I
recomm	end that they a	re capp	ed.			·		<del> </del>	
								<u> </u>	
Needed	Extra Permit Co								
		·			•				
				<del> </del>					
	<del></del>				<del></del>				<del></del>
		•		<del></del> _	<del> </del>				<del></del>
	<del></del>							<del></del>	
	<del></del>								
Groundw	ater Impact Pot	ential_	Possible	exfiltrat	ion of	wastew	ater from	the fi	rst two
settli	ng ponds.	_							
							_		
<del></del> -	·			<del></del>				<del></del>	
				<del></del>	<del></del>	<del></del>			
<del></del>	<del></del>	<del></del>							
II. M	DNITORING					•			
cation	and Type of F1	ow Meas	uring Equ	ipment	9" effl	uent p	arshall f	Lume	
				Accurate	and Cal	ibrate	ed ves		
ah dada	ng DMR Analysis	Rocky ?	Mountain						<del></del>
								<del></del>	
MR Anal	yses According	to Appr	oved Proc	cedures ye	s	<del></del>		· 	<del></del>
omments				····			·		
ivsinal	Description Re						iver.		

#### IV. COMPLIANCE/ENFORCEMENT

Person Interviewed Neil Muldoon, 967-2871

CDH Engineer James B. Horn

Comments Operator is doing a very good Job.

